

the play inspection company

Annual Inspection

Thurrock Council

Corringham Town Park

Springhouse Road, Corringham, Essex, SS17 7NB















RPII Inspection Methodology

This document outlines the RPII position on inspections undertaken by the Inspectors listed on the RPII Register of Inspectors for Indoor Annual, Outdoor Operational and Outdoor Routine.

Inspections are undertaken with reference to the standards listed in this preamble only; where no date for the standard is given it the date of the standard will be that current at the time of inspection with the exception of where overlap periods are granted by the standards committee when standards are updated. The information contained in reports is provided to assist the owner/operator in fulfilling their responsibilities as detailed in the relevant standard. Other standards referenced within the listed standards do not form part of the inspection.

The following standards are relevant to all installations of equipment that are publicly accessible to users; this would include public parks, pay and play parks, schools, nurseries, public houses, holiday parks, indoor play centres, farm parks etc. All equipment used or employed in publicly accessible areas should meet with the requirements of the relevant standards (listed below);

BS EN 1176 Parts 1, 2, 3, 4, 5, 6, 10 & 11 Playground equipment intended for permanent installation outdoors & indoors.

BS EN 1176 Part 7 - 'Guidance on Installation, Inspection, Maintenance and Operation' (this document gives guidance to the owners/operators of the facility on the installation, inspection, maintenance and operation of playground equipment, including ancillary items).

Domestic play equipment falls outside of the scope of BS EN 1176 and has its own standard (BS EN 71 – Safety of Toys). Where domestic equipment can be identified this will be acknowledged in the report but any comments concerning compliance within the inspection will still refer to BS EN 1176.

Other equipment that is not clearly identified as unsupervised or domestic (natural play, self-build equipment etc.) will be assessed for compliance with the relevant standard listed below:

BS EN 15312 - Free access multi-sports equipment

BS EN 14974 - Skateparks

BS EN 16630 - Permanently installed outdoor fitness equipment

BS EN 16899 - Parkour equipment (plus RPII/API guidance notes)

Annual and Post Installation inspections will take into consideration compliance with current standards and defects related to wear and vandalism. Items not listed in the report have not been included in the inspection. The inspection will cover the playground equipment and the active area up to 3.0 metres around, or the fence line if closer.

Operational inspections only take into consideration defects related to wear and vandalism. Routine visual inspections (if undertaken) relate only to the most obvious defects such as broken or missing parts, vandalism and issues created by severe weather conditions (the intention is to identify hazards created by storm damage).

The inspection is non-dismantling, non-destructive and does not include for any structural, toxicology or impact assessments defined in the standard; however, the inspector will undertake a manual test for stability and if equipment fails under manual load, or any other hazard is identified as an unacceptable risk, the owner/operator will be notified as soon as practicably possible.

The inspector will access all standing surfaces as necessary on the equipment and assess all parts up to 2.5m above the standing surface. Where it is not possible to access parts of the equipment without employing an alternative means of access the report will record the action required by the owner/operator to ensure the continued safe use of the equipment. Ancillary equipment will be assessed using the inspector's knowledge and experience of the standards named in this document to ensure as far as is reasonably practicable the continued safe use of the items concerned. The owner/operator is responsible for the overall safety of the equipment and area. Inspectors who are trained to use ladders may use them where it is safe to do so, but if members of the public are present on-site ladders may not be used to access the equipment.

The inspector will not undertake any of the following works unless specifically agreed in writing at the time of order:

Checking the depth and underlying structural integrity of any surface areas and/or carrying out any testing of impact absorbing properties of any surfaces. The identification of any corrosion, rot or other deterioration in any apparatus or equipment other than by an external inspection or the inspection of any equipment (or part thereof) that is underground. Tightening any bolts, hinges or other fixing devices on any apparatus or equipment. Assessing or inspecting any electrical installations contained on any site and/or apparatus and/or equipment. Assessing or inspecting any water supplies and/or water features and/or any associated computerised systems (including carrying out any programming).

Where planting or trees are mentioned in the report no aboricultural or horticultural assessments of toxicity, suitability or condition are undertaken; the owner/operator should have suitable inspections provided by a competent person.

The owner/operator should have a 'design risk assessment' provided by the manufacturer/designer of the area for the equipment and location in which the facility is installed.

The operator is responsible for managing risks of their provision and is required by law to carry out a 'suitable and sufficient assessment' of the risks associated with a site or activity and this inspection shall be considered as contributing to the operator's discharge of this responsibility.

The details contained within the report are a snapshot of the condition at the time of inspection only and subsequent events may affect the condition of the facility. Suggested remedial actions are based on the knowledge and experience of the inspector and/ or that of the inspection company. The owner/operator should seek the advice of the manufacturer or a competent person at all times when undertaking repairs and/or modifications to equipment.

A full copy of the Play Inspection Company Ltd. Terms & Conditions is available on our website (www.playinspections.co.uk)

© The Play Inspection Company & the Register of Play Inspectors International 9th September 2020





Table 1

The operator is responsible for following the guidance of the relevant standards. The standards give guidance on the installation, inspection, maintenance and operation of the various types of facilities. The inspection guidance is listed in Table 1, with an indication of which parts will be included in an RPII Annual or Post-Installation Inspection. The relevant standards also contain additional parts which the operator should follow.

Inspection recommendations of relevant standards Refer to relevant standards for full text	Annual Main	RPII Annual Outdoor/ Fully enclosed Inspection
6.1 d) Overall levels of safety of equipment (see note 1)	~	✓ [1]
6.1 d) Overall levels of safety of foundations (see note 1)	~	✓ [1]
6.1 d) Overall levels of safety of playing surfaces (see note 2)	•×	✓ [2]
6.1 d) Compliance with the relevant parts of the standard and or risk assessment (see note 3)	C.	V [3]
6.1 d) Effects of weather	\	\
6.1 d) Presence of rot, decay or corrosion (see note 1)) · · · · ·	✓ [1]
6.1 d) Assessment of repairs made or added or replaced components (see note 4)	~	✓ [4]
6.1 d) Excavation or dismantling/additional measures	7(4)	×
6.2.1 Assessment of glass reinforced plastics (see note 5)		✓ [5]
6.2.1 Inspection of one post equipment (see note 1)	\ \ \	✓ [1]
6.2.4 Undertaking the Operators inspection protocol	✓	×

NB: The clause numbers in table 1 are taken from BS EN 1176 - Part 7:2020. The content is equally applicable to all other relevant standards listed herein. Playgrounds contain a range of equipment from different manufacturers and installed over a number of years; operators should implement any guidance provided by the manufacturer. Item specific detail is not readily available to RPII Playground Inspectors, whose report contributes to the operator's overall Annual Main Inspection as detailed in the relevant standards.

- [1] A manual test only is undertaken for stability. Wear and instability are only detectable where readily apparent without dismantling or destruction and without the use of tools, excavation or specialist equipment. Rot and corrosion are tested or with a hammer and/or steel rod. Decay in timber may exist which can only be found with specialist equipment.
- [2] Only the visible condition and dimensional compliance of surface extent is considered. Neither testing of impact attenuating properties nor measurement of the thickness of bound surfaces are undertaken on RPII annual inspections.
- [3] The inspection assesses compliance where this can be tested on site using manual methods without dismantling, destruction and without the use of tools or specialist equipment.
- [4] The operator should use manufacturer's recommended parts, or equivalent. We are unable to verify if such parts have been used, and any subsequent change in quality or performance
- [5] Visible glass fibres will be noted in reports. The operator is responsible for repairs or replacement.

Risk Assessment Matrix

			Scores in the report are multiplication factors of Likelihood x Severity						
			Severity>>						
Likelihood	Very High probability, if the situation is not addressed an accident is almost certain.	5	Very High	VL (5)	L (10)	M (15)	H (20)	VH (25)	
	High probability an accident is probable without any added factor.	4	High	VL (4)	L (8)	M (12)	H (16)	H (20)	
	Moderate probability an incident is foreseeable.	3	Moderate	VL (3)	L (6)	L (9)	M (12)	M (15)	
	Some probability, requires a combination of factors to take place.	2	Low	VL (2)	VL (4)	L (6)	L (8)	L (10)	
	No significant probability; lightning strike, freak accident.	1	Very Low	VL (1)	VL (2)	VL (3)	VL (4)	VL (5)	
			4	Very Low	Low	Moderate	High	Very High	
			1	2	3	4	5		
PI				No injury likely e.g. damaged or soiled clothing, minor bruising, grazes	Minor injury, laceration or bruising requiring first aid only	Injury requiring medical intervention e.g. cuts requiring stitches	Serious injury including concussions or fracture of long bones	Severe injury involving a potential life changing injury or fatality	
				Severity>>					

Note 1: The total risk scores included within our reports are a multipication factor of the calculated Likelihood and Severity of each finding. Both Likelihood and Severity are given a number between 1 - 5 as shown on the matrix above and these two numbers are then multiplied together to give the total risk score that is shown against defects on the report. Total risk scores can be divided in both directions, i.e. a total risk score of 12 could be a Likelihood (3) x Severity (4) or Likelihood (4) x Severity (3).

Note 2: When we inspect we only see a snapshot of the current condition of the equipment. It is the operators responsibility to ensure that there is a continuing level of maintenance to keep the equipment in good working order and the site fit for use.

Equipment has been assessed to the following standards where relevant:

BS EN 1176 Parts 1-11 (Playground equipment and surfacing)

BS EN 14974 (Facilities for users of roller sports equipment)

BS EN 15312 (Free access multi-sports equipment)

BS EN 16899 (Parkour Equipment)

BS EN 16630 (Outdoor Fitness Equipment).



Corringham Town Park

Inspection Ref: 1429378 Site Ref: 52819

Inspected: 31-July-2021 - 04:31 by Lyn Williams RPII Annual Inspector

Risk Assessment: 12 Moderate Risk



Location:

The site is located in an area of public open space and is overlooked by a number of properties in the local community. **Disabled Access:**

Generally accessible; an area accessible to most.





9 - Low Risk

Item: Site General Manufacturer: Owner/Operator

Surface Type: N/A **Item Quantity:** 1 **Equipment Compliance:** N/A Surface Area Compliance: N/A

Total Findings: 14



Finding 1

There are stress fractures in the tarmac footpath - Monitor

Finding 2

There are areas or parts of the timber edgings that have rotted or are missing - Replace all affected timbers

Finding 3

There are trip hazards at the edges of the surface -Reinstate surrounding surface levels to remove the trip points

Finding 4

There are significant gaps (over 30mm) between the surface and the edging or between the joints in the surface; these are large enough for a small foot to enter - Repair surfacing

Finding 5

The surface is lifting at the edges and creating trip points -Repair perimeter of surfacing to remove trip points

Finding 6

The surfacing in the fitness area is damaged - Repair the damaged areas of surfacing

Finding 7

There is evidence of fire damage to the surfacing in the fitness area - Monitor for any further deterioration and repair as required

Finding 8

There are weeds/vegetation growth between or around the edges of the loose fill surfacing - Remove weeds/vegetation growth

Finding 9

The sand safety surface is low and the membrane is exposed creating trip points - Remove or resecure the exposed membrane and top up the surface to the correct level

Finding 10

The grass has rooted in the sand creating trip hazards -Provide a uniform surface

Finding 11

The loose fill safety surfacing has become compacted and degraded to mulch - Top up with fresh material

Finding 12

The bark safety surface is low and the membrane is exposed creating trip points - Remove or resecure the exposed membrane and top up the surface to the correct level

Finding 13

There are sleepers missing from the timber retaining wall -Replace the missing sleepers

Finding 14

There is litter/debris in the fitness area - Remove litter/debris from the area and maintain



5 - Very Low Risk

Item: Sign

Manufacturer: Not Applicable

Surface Type: N/A **Item Quantity:** 1 **Equipment Compliance:** N/A Surface Area Compliance: N/A

Total Findings: 3



Finding 1

It is recommended that signage, with information including the site address, contact information for maintenance issues equipment in accordance with the requirements of BS EN and emergency contact details are provided for the facility -Provide in accordance with the recommendations


Finding 3

There are no instruction labels provided on the fitness equipment; an instruction label should be provided with each item of equipment in accordance with the requirements of BS EN 16630 - Provide appropriate instruction label/s

Finding 2

Signage should be provided for the outdoor fitness 16630, key requirements of the sign include, but are not limited to, intended users, medical safety and emergency contact details - Provide appropriate signage





Item: Gate - Self Closing Manufacturer: Owner/Operator

Surface Type: Grass **Item Quantity:** 1 **Equipment Compliance:** N/A Surface Area Compliance: N/A

Total Findings: 6



Finding 1

The gate is not operating correctly - Take effective action to ensure the gate closes between 4 and 8 seconds

Finding 3

The concrete around the post has sheared and the post is loose in the foundations - Reset the post

Finding 5

The weld(s) on this item have failed - Repair item

Finding 2

No slamming plate has been fitted to the gates and the gate leaves pass the slamming posts - Provide slamming plates

Finding 4

There is algae or moss on the surface of the gate - Clean and treat appropriately

Finding 6

The area around the item has eroded and may become slippery - Reinstate eroded area

8 - Low Risk

Gate - Maintenance Item: Owner/Operator Manufacturer:

Surface Type: Grass

Item Quantity:

N/A **Equipment Compliance:** Surface Area Compliance: N/A

Total Findings: 3



Finding 1

The gate has no drop bolt sleeves and/or drop bolts fitted - The maintenance gate isn't locked - Secure the gate Provide drop bolt sleeves and/or drop bolts

Finding 3

The item is loose in its foundations - Reinstall item to secure

Finding 2





6 - Low Risk

Item:Fence - Bow TopManufacturer:Owner/Operator

Surface Type: Grass Item Quantity: 1
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 1



Finding 1

There is some damage to the fence sections - Monitor for any further deterioration and repair as required



8 - Low Risk

Item:Swing BarrierManufacturer:Not Identified

Surface Type: Grass Item Quantity: 2
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 2



Finding 1

The area around the item has eroded and may become slippery - Reinstate eroded area

Finding 2

The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting - Treat any rusting components and repaint



8 - Low Risk

Item: Bench

Owner/Operator Manufacturer:

Surface Type: Grass **Item Quantity:** 2 **Equipment Compliance:** N/A Surface Area Compliance: N/A

Total Findings: 1



Finding 1

The area around the item has eroded and may become slippery - Reinstate eroded area

8 - Low Risk

Item: Picnic Table Manufacturer: Owner/Operator

Surface Type: Concrete

Item Quantity: 3 **Equipment Compliance:** N/A Surface Area Compliance: N/A

Total Findings:



Finding 1

There is some graffiti present - Remove the graffiti

Finding 2


There is evidence of fire damage to the item - Treat and repaint as required

Finding 3

The concrete bases are damaged - Repair the damaged

concrete





Item:Picnic TableManufacturer:Owner/Operator

Surface Type: Tarmac Item Quantity: 1
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 3



There is moderate damage to the tarmac surface - Repair the damaged areas of surfacing

Finding 1

There is evidence of fire damage to the item - Monitor for any further deterioration and repair as required

Finding 3

Parts of the timber are rough or splintered - Remove all rough or sharp edges



Item:Litter BinManufacturer:Owner/Operator

Surface Type:GrassItem Quantity:2Equipment Compliance:N/ASurface Area Compliance:N/A

Total Findings:



Finding 1

The bin is not securely fixed to the surface and there is some possibility of the item tipping or rolling over - Secure the bin to the ground




10 - Low Risk

Item:BMX TrackManufacturer:Owner/Operator

Surface Type: Tarmac Item Quantity: 1

Equipment Compliance: N/A **Surface Area Compliance:** N/A

Total Findings: 4



There is some evidence of rot in the timber - Monitor for any further deterioration and replace as required

Finding 1

BMX tracks are not currently covered by any British or European Standard; comments made in the report are based on the application of our knowledge and understanding of the Wheeled Sports Standard (BS EN 14974) and their maintenance and the area has been risk assessed accordingly - Monitor use and review risk assessment regularly


Finding 3

There are minor stress fractures in the tarmac surface - Monitor and repair if required

Finding 4

The edges of the tarmac jump ramps has subsided - Repair the damaged ramps





Multi Play (Toddler) Item:

Manufacturer: Hags **Surface Type:** Sand

Item Quantity:

Equipment Compliance: Yes Surface Area Compliance: Yes

Life Expectancy: 5 -10 Years

Total Findings: 5

Finding 1

There are a number of dents in the slide surface - Monitor for any further deterioration and repair as required

There are post / end caps missing from the item - Replace

missing post caps

Finding 5

There is some evidence of rot in the timber - Monitor for any further deterioration and replace as required



Finding 2

The timber stain is in poor condition - Prepare all affected parts and re-stain with an appropriate preservative

Finding 4

Parts of the timber are rough or splintered - Remove all rough or sharp edges



8 - Low Risk

Item: 1 Bay 2 Seat (Cradle) Manufacturer: Wicksteed Playgrounds

Surface Type: Matta

Item Quantity:

Equipment Compliance: Yes Surface Area Compliance: Yes

Life Expectancy: 5 - 10 Years

Total Findings: 6

Finding 1

There are gaps opening in between the tiles - Repair as

required

Finding 3 The chain links are worn in excess of 40% and require

renewing - Replace worn chains

Finding 5

The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting - Treat any

rusting components and repaint

Finding 2

The chain openings are in excess of the 8.6mm as recommended by BS EN 1176 - Monitor - No remedial work

recommended

Finding 4

The connecting lugs are showing signs of wear - Monitor

for any further deterioration and repair as required

Finding 6

The seat has minor damage or wear - Monitor for any

further deterioration and replace as required







6 - Low Risk

Multi Play (Junior) Item:

Manufacturer: Hags

Surface Type: Woodchip

Item Quantity:

Equipment Compliance: No

Surface Area Compliance: Yes

Life Expectancy: 5 - 10 Years

Total Findings: 7



The height of the slide runout is in excess of 350mm and fails the requirements of BS EN 1176: Part 3 - Monitor - No remedial work recommended

Finding 3

There is evidence of fire damage to the item - Monitor for any further deterioration and repair as required

Finding 5

There is/are finger entrapment/s in the structure and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6 Entrapment of fingers - Monitor - No remedial work recommended

Finding 7

Manufacturer:

There are a number of dents in the slide surface - Monitor for any further deterioration and repair as required



Finding 2

There are post / end caps missing from the item - Replace missing post caps

Finding 4

Parts of the timber are rough or splintered - Remove all rough or sharp edges

Finding 6

There is algae or moss on the surface of the equipment -Clean and treat appropriately



4 - Very Low Risk

Cone Climber Item: Not Identified

Woodchip **Surface Type:**

Item Quantity:

Equipment Compliance: Yes Surface Area Compliance: Yes

Life Expectancy: 5 -10 Years

Total Findings: 1

Finding 1

This item is satisfactory - no work required -





1

8 - Low Risk

Item: Misc Item

Manufacturer: Playworld Systems (Europe) Ltd

Surface Type: Woodchip

Item Quantity: 1

Equipment Compliance: Yes **Surface Area Compliance:** Yes

Life Expectancy: 1 - 3 Years

Total Findings: 2

Finding 1

The item has missing component(s) - Consider replacing

missing components



Finding 2

The bearing is not operating correctly - Repair or replace

the bearing as required



6 - Low Risk

Item: Spinning Pole

Manufacturer: Playworld Systems (Europe) Ltd

Surface Type: Woodchip

Item Quantity: 1

Equipment Compliance: Yes

Surface Area Compliance: Yes

Life Expectancy: 3 - 5 Years

Total Findings: 2



Finding 1

The item has missing component(s) - Consider replacing

missing components

Finding 2

There is/are missing components creating finger entrapment/s in the redundant bolt holes and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6 Entrapment of fingers - Replace the missing components





6 - Low Risk

Item: Stepping Stones

Manufacturer: Playworld Systems (Europe) Ltd

Surface Type: Woodchip

Item Quantity: 1

Equipment Compliance: Yes **Surface Area Compliance:** Yes

Life Expectancy: 3 - 5 Years

Total Findings: 1

Finding 1

There is minor movement of the tops on the posts - Monitor



F

9 - Low Risk

Item:Climbing WallManufacturer:Not Identified

Surface Type: Woodchip

Item Quantity: 1

Equipment Compliance: Yes

Surface Area Compliance: Yes

Life Expectancy: 5 - 10 Years

Total Findings: 2



Finding 1

The rope has worn and wire strands are exposed - Replace

rope or net

Finding 2

The ropes on this item have been taped and we are unable to fully assess the condition of the rope, ensure no wire strands are broken beneath the tape - Repair or replace as required





8 - Low Risk

Item:Space NetManufacturer:Kompan LtdSurface Type:Woodchip

Item Quantity: 1

Equipment Compliance: No

Surface Area Compliance: Yes

Life Expectancy: 5 -10 Years

Total Findings: 3



There are holes in surface adjacent to the item - Infill to provide a sound reasonably level surface.

Finding 3

There is a potential crushing point between the rope and the central post in contravention of BS EN 1176 Part 1 - Retension ropes to ensure the rope is spaced evenly around the post



Finding 2

The ropes/nets are worn/damaged in places - Monitor for any further deterioration and repair or replace as required



2 - Very Low Risk

Item: 2 Bay Swing

Manufacturer: Playworld Systems (Europe) Ltd

Surface Type: Woodchip

Item Quantity: 1

Equipment Compliance: N/A
Surface Area Compliance: N/A

Life Expectancy: 5 -10 Years

Total Findings: 2

Finding 1

The item has missing component(s) - Consider replacing

missing components



Finding 2

There is some graffiti present - Remove the graffiti



6 - Low Risk

Item: 1 Bay 2 Seat (Flat)

Manufacturer: Wicksteed Playgrounds

Surface Type: Wet Pour

Item Quantity:

Equipment Compliance: No

Surface Area Compliance: Yes

Life Expectancy: 5 - 10 Years

Total Findings: 6

Finding 1

The safety surface around the area is beginning to wear -

Monitor for any further deterioration and repair as required

Finding 3

The chain openings are in excess of the 8.6mm as recommended by BS EN 1176 - Monitor - No remedial work recommended

Finding 5

The connecting lugs are showing signs of wear - Monitor for any further deterioration and repair as required

Finding 2

The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting - Treat any rusting components and repaint

Finding 4

There is some notable evidence of chain wear - Monitor for any further deterioration and replace when 40% worn

Finding 6

The seat has minor damage or wear - Monitor for any further deterioration and replace as required



12 - Moderate Risk

Item:Cable RunwayManufacturer:Not Identified

Surface Type: Woodchip

Item Quantity: 1
Equipment Compliance: No

Surface Area Compliance: Yes

Life Expectancy: 5 -10 Years

Total Findings: 15

Finding 1

We have completed a visual inspection of the cable and fixing points from ground level, however it is not possible to fully inspect the cable and fixings without either hiring equipment to gain access or removing the cable and inspecting at ground level. We recommend that the main cable and fixing security is thoroughly inspected at least in accordance with the manufacturers recommendations to check for damage, security or internal rusting, this will help to ensure the continued safe use of the equipment - Inspect in accordance with the manufacturers recommendations

Finding 3

There are areas or parts of the timber on the structure that have rotted - Replace all affected timbers

Finding 5

There are holes in surface - Infill to provide a sound reasonably level surface.

Finding 7

The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process - Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability

Finding 9

The traveller brake isn't working - Repair the damaged traveller brake



Finding 2

There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the rotting process - Monitor for any deterioration (rot) and replace as required

Finding 4

The edges of the grass mat surface have not been installed in accordance with the API Code of Practice - Tuck in edges of grass mat to remove trip hazards

Finding 6

The seat is less than 2.0 metres from the post when extended at 45 degrees at the end of the area of travel and does not meet the requirements of BS EN 1176 Part 4 - Adjust the cable stop position to ensure the minimum distance is maintained

Finding 8

The dampening spring or tyre is damaged or broken on the item - Replace spring or tyre

Finding 10

The nylon inserts are worn or missing at the point the cable enters the traveller - Replace worn or missing inserts as required



Finding 11

The cableway seat has been damaged - Monitor for any further deterioration and replace as required

Finding 12

The chain openings are in excess of the 8.6mm as recommended by BS EN 1176 - Monitor - No remedial work recommended

Finding 13

The chain links are worn in excess of 40% and require renewing - Replace worn chains

Finding 14

The chain/rope covering is damaged or missing - Replace as required

Finding 15

The area around the item has eroded and may become slippery - Reinstate eroded area

6 - Low Risk

Item: Leg Press

The Great Outdoor Gym Company Manufacturer:

Surface Type: Wet Pour

Item Quantity: Equipment Compliance: No Surface Area Compliance: Yes


Life Expectancy: 3 - 5 Years

Total Findings: 2

Finding 2

There is minor distortion damage to the item - Monitor and repair if required

There is some minor damage to the surface - Monitor for







6 - Low Risk

Item: Ab Station

Manufacturer: The Great Outdoor Gym Company

Surface Type: Wet Pour

Item Quantity: 1

Equipment Compliance: No

Surface Area Compliance: Yes

Life Expectancy: 5 -10 Years

Total Findings: 2



The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting - Treat any

rusting components and repaint



Finding 2

There is minor distortion damage to the bench - Monitor and

repair if required



8 - Low Risk

Item: Cycle

Manufacturer: The Great Outdoor Gym Company

Surface Type: Wet Pour

Item Quantity: 2

Equipment Compliance: No

Surface Area Compliance: Yes

Life Expectancy: 1 - 3 Years

Total Findings: 4



Finding 2

The mechanism has been removed from one item - Replace There is algae or moss on the surface of the equipment -

Clean and treat appropriately



Finding 1

Finding 3

There is minor damage to the seat - Monitor and replace if required

Finding 4

The base plates have been removed from one cycle -

Replace the base plates





12 - Moderate Risk

Item: Hip Twister

Manufacturer: The Great Outdoor Gym Company

Surface Type: Wet Pour

Item Quantity: 1

Equipment Compliance: N/A Surface Area Compliance: N/A

Life Expectancy: <12 Months

Total Findings: 3

Finding 1 Finding 2

The deflection of the rotating user station exceeds the maximum 105 degrees required by BS EN 16630 - Monitor -No remedial work recommended

guideline of user direction and/or the original position as required by BS EN 16630 - Monitor - No remedial work

The rotating user station is not appropriately marked with a

recommended

Finding 3

The central support is missing - Replace the missing support or remove the item completely

8 - Low Risk

Hand Bike Item:

The Great Outdoor Gym Company Manufacturer:

Wet Pour **Surface Type:**

1 **Item Quantity:**

Equipment Compliance: Ν̈́ο **Surface Area Compliance:** Yes

3 - 5 Years Life Expectancy:

Total Findings: 2

Finding 1 Finding 2

There is minor damage to the seat - Monitor and replace if One or more handgrip(s) are damaged or missing. required

Replace missing or damaged handgrips





8 - Low Risk

Item: Treadmill

Manufacturer: The Great Outdoor Gym Company

Surface Type: Wet Pour

Item Quantity: 1

Equipment Compliance: No

Surface Area Compliance: Yes

Life Expectancy: 5 -10 Years

Total Findings: 2



The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting - Treat any

rusting components and repaint



Finding 2

The inspection plate has been removed - Replace the missing inspection plate

🎧 6 - Low Risk

Item: Pull Up Station

Manufacturer: The Great Outdoor Gym Company

Surface Type: Wet Pour

Item Quantity: 1

Equipment Compliance: No

Surface Area Compliance: Yes

Life Expectancy: 5 -10 Years

Total Findings: 1

Finding 1

The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting - Treat any rusting components and repaint





6 - Low Risk

Item: Dip Station

Manufacturer: The Great Outdoor Gym Company

Surface Type: Wet Pour

Item Quantity: 1

Equipment Compliance: No

Surface Area Compliance: Yes

Life Expectancy: 5 -10 Years

Total Findings: 1

Finding 1

The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting - Treat any rusting components and repaint



8 - Low Risk

Item: Cross Trainer

Manufacturer: The Great Outdoor Gym Company

Surface Type: Wet Pour

Item Quantity: 2

Equipment Compliance: No

Surface Area Compliance: Yes

Life Expectancy: 3 - 5 Years


Total Findings:

Finding 1

Finding 2

There is or are fixings missing on the item - Replace all
The bushes are worn or missing - Replace worn or missing

missing fixings bushes





8 - Low Risk

Item: Traverse Wall

Manufacturer: Park Leisure Ltd

Surface Type: Wet Pour

Item Quantity: 1

Equipment Compliance: Yes **Surface Area Compliance:** Yes

Life Expectancy: 5 -10 Years

Total Findings: 3

Finding 1 Finding 2

The surfacing is severely damaged - Repair damaged areas There is or are fixings missing on the item - Replace all of surfacing missing fixings

Finding 3

The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting - Treat any rusting components and repaint





6 - Low Risk

Item: Goalmouth and Basketball Post

Manufacturer: Park Leisure Ltd

Surface Type: Wet Pour

Item Quantity:

Equipment Compliance: No

Surface Area Compliance: N/A

Life Expectancy: 5 - 10 Years

Total Findings: 4

Finding 1

A clearly visible facility sign should be provided in a prominent position with the wording as detailed BS EN 15312- the equipment is not intended for children less than 3 years old- the warning - Do not climb on the framework or remedial work recommended nets- the warning - Do not hang on the ring (if provided)- the warning - Do not wear rings or other jewellery- name and telephone number of the administrator- number to call in case of accident - Provide signage to BS EN 15312

There is some graffiti present - Remove the graffiti



There is/are finger entrapments in the mesh openings and the item fails to meet the requirements of BS EN 15312 Clause 4.4.2.2 Entrapment of fingers - Monitor - No

Finding 4

There is algae or moss on the surface of the equipment -Clean and treat appropriately





8 - Low Risk

Item: Kickabout Wall

Manufacturer: Park Leisure Ltd

Surface Type: Wet Pour

Item Quantity: 1

Equipment Compliance: Yes **Surface Area Compliance:** Yes

Life Expectancy: 5 -10 Years

Total Findings: 4

Finding 1

A clearly visible facility sign should be provided in a prominent position with the wording as detailed BS EN 15312- the equipment is not intended for children less than 3 years old- the warning - Do not climb on the framework or nets- the warning - Do not hang on the ring (if provided)- the warning - Do not wear rings or other jewellery- name and telephone number of the administrator- number to call in case of accident - Provide signage to BS EN 15312

Finding 3

There is some graffiti present - Remove the graffiti



Finding 2

There is or are fixings missing on the item - Replace all missing fixings

Finding 4

The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting - Treat any rusting components and repaint





Findings information









Item: Ancillary Items - Site General Risk Level: L - Low Risk

Manufacturer: Owner/Operator Surface: N/A






Finding: There are areas or parts of the timber edgings that **Action:** Replace all affected timbers have rotted or are missing

8 - Low Risk (Finding 3)







Action: Reinstate surrounding surface levels to remove the trip points







9 - Low Risk (Finding 4)

Ancillary Items - Site General Risk Level: Item:

Owner/Operator Manufacturer:



Surface: N/A

L - Low Risk

Finding: There are significant gaps (over 30mm) between the surface and the edging or between the joints in the surface; these are large enough for a small foot to enter

Action: Repair surfacing

8 - Low Risk (Finding 5)

Item: Ancillary Items - Site General Risk Level: L - Low Risk Owner/Operator Manufacturer: Surface: N/A






Finding: The surface is lifting at the edges and creating trip Action: Repair perimeter of surfacing to remove trip points points














Item: Ancillary Items - Site General Risk Level: L - Low Risk

Manufacturer: Owner/Operator Surface: N/A



Finding: There is evidence of fire damage to the surfacing in the fitness area



6 - Low Risk (Finding 8)



Finding: There are weeds/vegetation growth between or around the edges of the loose fill surfacing



Action: Remove weeds/vegetation growth







Ancillary Items - Site General Risk Level: L - Low Risk Item:

Manufacturer: Owner/Operator Surface: N/A





Finding: The sand safety surface is low and the membrane Action: Remove or resecure the exposed membrane and is exposed creating trip points

top up the surface to the correct level

8 - Low Risk (Finding 10)






Finding: The grass has rooted in the sand creating trip hazards

Action: Provide a uniform surface







Item: Ancillary Items - Site General Risk Level: L - Low Risk

Manufacturer: Owner/Operator Surface: N/A



Finding: The loose fill safety surfacing has become compacted and degraded to mulch



Action: Top up with fresh material

8 - Low Risk (Finding 12)



Finding: The bark safety surface is low and the membrane is exposed creating trip points



Action: Remove or resecure the exposed membrane and top up the surface to the correct level








Item: Ancillary Items - Site General Risk Level: L - Low Risk


Manufacturer: Owner/Operator Surface: N/A





6 - Low Risk (Finding 14)







Action: Remove litter/debris from the area and maintain





5 - Very Low Risk (Finding 1)

Item: Ancillary Items - Sign Risk Level: V - Very Low Risk

Manufacturer: Not Applicable Surface: N/A



Finding: It is recommended that signage, with information including the site address, contact information for maintenance issues and emergency contact details are provided for the facility



Action: Provide in accordance with the recommendations







Item: Ancillary Items - Sign Risk Level: V - Very Low Risk

Manufacturer: Not Applicable Surface: N/A





Finding: Signage should be provided for the outdoor fitness **Action:** Provide appropriate signage equipment in accordance with the requirements of BS EN 16630, key requirements of the sign include, but are not limited to, intended users, medical safety and emergency contact details







4 - Very Low Risk (Finding 3)

Ancillary Items - Sign Item:

Not Applicable Manufacturer:

V - Very Low Risk Risk Level:

Surface: N/A



Finding: There are no instruction labels provided on the fitness equipment; an instruction label should be provided with each item of equipment in accordance with the requirements of BS EN 16630



Action: Provide appropriate instruction label/s



5 - Very Low Risk (Finding 1)

Item: Gates - Gate - Self Closing


Manufacturer: Owner/Operator

V - Very Low Risk Risk Level: Surface:

Grass



Finding: The gate is not operating correctly



Action: Take effective action to ensure the gate closes between 4 and 8 seconds







Item:Gates - Gate - Self ClosingRisk Level:L - Low RiskManufacturer:Owner/OperatorSurface:Grass





Finding: No slamming plate has been fitted to the gates and **Action:** Provide slamming plates the gate leaves pass the slamming posts

8 - Low Risk (Finding 3)

Item:Gates - Gate - Self ClosingRisk Level:L - Low RiskManufacturer:Owner/OperatorSurface:Grass





Finding: The concrete around the post has sheared and the **Action:** Reset the post post is loose in the foundations









































Finding: The paintwork on this item has been damaged or Action: Treat any rusting components and repaint worn exposing the metal underneath which is rusting



Annual Inspection for Thurrock Council at Corringham Town Park Springhouse Road, Corringham, Essex, SS17 7NB Inspected on the 31-July-2021 - 04:31































Item:Ancillary Items - Litter BinRisk Level:L - Low RiskManufacturer:Owner/OperatorSurface:Grass



Finding: The bin is not securely fixed to the surface and there is some possibility of the item tipping or rolling over



Action: Secure the bin to the ground

10 - Low Risk (Finding 1)

Item:Wheeled Sports - BMX TrackRisk Level:L - Low RiskManufacturer:Owner/OperatorSurface:Tarmac




Finding: BMX tracks are not currently covered by any British or European Standard; comments made in the report are based on the application of our knowledge and understanding of the Wheeled Sports Standard (BS EN 14974) and their maintenance and the area has been risk assessed accordingly



Action: Monitor use and review risk assessment regularly








Item:Wheeled Sports - BMX TrackRisk Level:L - Low RiskManufacturer:Owner/OperatorSurface:Tarmac







Action: Monitor for any further deterioration and replace as required

6 - Low Risk (Finding 3)

Item:Wheeled Sports - BMX TrackRisk Level:L - Low RiskManufacturer:Owner/OperatorSurface:Tarmac



Finding: There are minor stress fractures in the tarmac surface



Action: Monitor and repair if required















6 - Low Risk (Finding 2)

Item:Activity Equipment - Multi Play (Toddler)Risk Level:L - Low RiskManufacturer:HagsSurface:Sand







Action: Prepare all affected parts and re-stain with an appropriate preservative

6 - Low Risk (Finding 3)

Item:Activity Equipment - Multi Play (Toddler)Risk Level:L - Low RiskManufacturer:HagsSurface:Sand



Finding: There are post / end caps missing from the item



Action: Replace missing post caps







Activity Equipment - Multi Play (Toddler) Risk Level: L - Low Risk Hags Surface: Sand





Finding: Parts of the timber are rough or splintered

Action: Remove all rough or sharp edges

6 - Low Risk (Finding 5)

Item:Activity Equipment - Multi Play (Toddler)Risk Level:L - Low RiskManufacturer:HagsSurface:Sand



Finding: There is some evidence of rot in the timber



Action: Monitor for any further deterioration and replace as required









recommended by BS EN 1176







Item:Swings - 1 Bay 2 Seat (Cradle)Risk Level:L - Low RiskManufacturer:Wicksteed PlaygroundsSurface:Matta



Finding: The chain links are worn in excess of 40% and require renewing



Action: Replace worn chains

6 - Low Risk (Finding 4)

Item:Swings - 1 Bay 2 Seat (Cradle)Risk Level:L - Low RiskManufacturer:Wicksteed PlaygroundsSurface:Matta



Finding: The connecting lugs are showing signs of wear



Action: Monitor for any further deterioration and repair as required







6 - Low Risk (Finding 5)

Item:Swings - 1 Bay 2 Seat (Cradle)Risk Level:L - Low RiskManufacturer:Wicksteed PlaygroundsSurface:Matta



Finding: The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting

Action: Treat any rusting components and repaint



6 - Low Risk (Finding 6)

Item:Swings - 1 Bay 2 Seat (Cradle)Risk Level:L - Low RiskManufacturer:Wicksteed PlaygroundsSurface:Matta





Finding: The seat has minor damage or wear

Action: Monitor for any further deterioration and replace as required







Item:Activity Equipment - Multi Play (Junior)Risk Level:L - Low RiskManufacturer:HagsSurface:Woodchip



Finding: The height of the slide runout is in excess of 350mm and fails the requirements of BS EN 1176: Part 3



Action: Monitor - No remedial work recommended



Item:Activity Equipment - Multi Play (Junior)Risk Level:L - Low RiskManufacturer:HagsSurface:Woodchip



Finding: There are post / end caps missing from the item



Action: Replace missing post caps







Item:Activity Equipment - Multi Play (Junior)Risk Level:L - Low RiskManufacturer:HagsSurface:Woodchip



Finding: There is evidence of fire damage to the item



Action: Monitor for any further deterioration and repair as required

6 - Low Risk (Finding 4)

Item:Activity Equipment - Multi Play (Junior)Risk Level:L - Low RiskManufacturer:HagsSurface:Woodchip



Finding: Parts of the timber are rough or splintered



Action: Remove all rough or sharp edges







5 - Very Low Risk (Finding 5)

Item: Activity Equipment - Multi Play (Junior)

Manufacturer: Hags



Finding: There is/are finger entrapment/s in the structure and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6 Entrapment of fingers

Risk Level: V - Very Low Risk Surface: Woodchip



Action: Monitor - No remedial work recommended

i

6 - Low Risk (Finding 6)

Item: Activity Equipment - Multi Play (Junior)

Manufacturer: Hags



Finding: There is algae or moss on the surface of the equipment

Risk Level: L - Low Risk Surface: Woodchip



Action: Clean and treat appropriately







4 - Very Low Risk (Finding 7)

V - Very Low Risk Activity Equipment - Multi Play (Junior) Risk Level: Surface: Woodchip

Manufacturer: Hags



Finding: There are a number of dents in the slide surface



Action: Monitor for any further deterioration and repair as required

6 - Low Risk (Finding 1)

Item: Rotor Play - Misc Item Risk Level: L - Low Risk Playworld Systems (Europe) Ltd Manufacturer: Surface: Woodchip



Finding: The item has missing component(s)



Action: Consider replacing missing components



















V - Very Low Risk Rotor Play - Spinning Pole Risk Level: Item: Playworld Systems (Europe) Ltd Woodchip Manufacturer: Surface:





Finding: There is/are missing components creating finger Action: Replace the missing components entrapment/s in the redundant bolt holes and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6

Entrapment of fingers

6 - Low Risk (Finding 1)

L - Low Risk Item: Activity Equipment - Stepping Stones Risk Level: Playworld Systems (Europe) Ltd Surface: Woodchip Manufacturer:






Finding: There is minor movement of the tops on the posts Action: Monitor
























8 - Low Risk (Finding 3)

Activity Equipment - Space Net Risk Level: L - Low Risk Item: Kompan Ltd Woodchip Manufacturer: Surface:



Finding: There is a potential crushing point between the rope and the central post in contravention of BS EN 1176 Part 1



Action: Re-tension ropes to ensure the rope is spaced evenly around the post

2 - Very Low Risk (Finding 1)

Swings - 2 Bay Swing Risk Level: V - Very Low Risk Item: Manufacturer: Playworld Systems (Europe) Ltd Surface: Woodchip



Finding: The item has missing component(s)



Action: Consider replacing missing components







Finding: There is some graffiti present Action: Remove the graffiti



wear required







6 - Low Risk (Finding 2)

Swings - 1 Bay 2 Seat (Flat) Risk Level: L - Low Risk Item: Wicksteed Playgrounds Surface: Wet Pour Manufacturer:





Finding: The paintwork on this item has been damaged or Action: Treat any rusting components and repaint worn exposing the metal underneath which is rusting

5 - Very Low Risk (Finding 3)

V - Very Low Risk Item: Swings - 1 Bay 2 Seat (Flat) Risk Level: Manufacturer: Wicksteed Playgrounds Surface: Wet Pour





Finding: The chain openings are in excess of the 8.6mm as Action: Monitor - No remedial work recommended recommended by BS EN 1176







6 - Low Risk (Finding 4)

Item:Swings - 1 Bay 2 Seat (Flat)Risk Level:L - Low RiskManufacturer:Wicksteed PlaygroundsSurface:Wet Pour



Finding: There is some notable evidence of chain wear



Action: Monitor for any further deterioration and replace when 40% worn

6 - Low Risk (Finding 5)

Item: Swings - 1 Bay 2 Seat (Flat)

Manufacturer: Wicksteed Playgrounds



Finding: The connecting lugs are showing signs of wear

Risk Level: L - Low Risk Surface: Wet Pour



Action: Monitor for any further deterioration and repair as required





6 - Low Risk (Finding 6)

Item:Swings - 1 Bay 2 Seat (Flat)Risk Level:Manufacturer:Wicksteed PlaygroundsSurface:

Risk Level: L - Low Risk
Surface: Wet Pour



Finding: The seat has minor damage or wear



Action: Monitor for any further deterioration and replace as required





1

0 - Risk Assessment not Undertaken (Finding 1)

Item: Other - Cable Runway

Manufacturer: Not Identified

Risk Level: Surface: N - Risk Assessment not Undertaken

: Woodchip



Finding: We have completed a visual inspection of the cable and fixing points from ground level, however it is not possible to fully inspect the cable and fixings without either hiring equipment to gain access or removing the cable and inspecting at ground level. We recommend that the main cable and fixing security is thoroughly inspected at least in accordance with the manufacturers recommendations to check for damage, security or internal rusting, this will help to ensure the continued safe use of the equipment



Action: Inspect in accordance with the manufacturers recommendations







Item: Other - Cable Runway

Manufacturer: Not Identified

Risk Level: L - Low Risk Surface: Woodchip



Finding: There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the rotting process



Action: Monitor for any deterioration (rot) and replace as required

12 - Moderate Risk (Finding 3)

Item: Other - Cable Runway

Manufacturer: Not Identified

Risk Level: M - Moderate Risk
Surface: Woodchip



Finding: There are areas or parts of the timber on the structure that have rotted



Action: Replace all affected timbers







Item: Other - Cable Runway


Manufacturer: Not Identified

Risk Level: L - Low Risk Surface: Woodchip





Finding: The edges of the grass mat surface have not been **Action:** Tuck in edges of grass mat to remove trip hazards installed in accordance with the API Code of Practice



Item: Other - Cable Runway

Manufacturer: Not Identified

Risk Level: L - Low Risk Surface: Woodchip





Finding: There are holes in surface

Action: Infill to provide a sound reasonably level surface.







8 - Low Risk (Finding 6)

Other - Cable Runway Risk Level: L - Low Risk Item: Manufacturer: Not Identified Surface: Woodchip





Finding: The seat is less than 2.0 metres from the post Action: Adjust the cable stop position to ensure the when extended at 45 degrees at the end of the area of travel minimum distance is maintained and does not meet the requirements of BS EN 1176 Part 4

6 - Low Risk (Finding 7)

Other - Cable Runway Risk Level: L - Low Risk Item: Manufacturer: Not Identified Surface: Woodchip





Finding: The timber has a number of splits/shakes or air Action: Monitor to ensure the splits do not cross through cracks and this may affect the stability or allow water ingress fixing points of the structure and/or cause any instability which will accelerate the rotting process







Item: Other - Cable Runway

Manufacturer: Not Identified

Risk Level: L - Low Risk Surface: Woodchip



Finding: The dampening spring or tyre is damaged or broken on the item



Action: Replace spring or tyre

8 - Low Risk (Finding 9)

Item: Other - Cable Runway

Manufacturer: Not Identified

Risk Level: L - Low Risk Surface: Woodchip



Finding: The traveller brake isn't working



Action: Repair the damaged traveller brake







5 - Very Low Risk (Finding 10)

Other - Cable Runway

Manufacturer: Not Identified



V - Very Low Risk Risk Level: Surface: Woodchip



Finding: The nylon inserts are worn or missing at the point Action: Replace worn or missing inserts as required the cable enters the traveller

L - Low Risk

6 - Low Risk (Finding 11)


Item: Other - Cable Runway


Manufacturer: Not Identified



Surface: Woodchip

Risk Level:











tem: Other - Cable Runway

Manufacturer: Not Identified

Risk Level: V - Very Low Risk Surface: Woodchip





Finding: The chain openings are in excess of the 8.6mm as **Action:** Monitor - No remedial work recommended recommended by BS EN 1176


8 - Low Risk (Finding 13)

Item: Other - Cable Runway

Manufacturer: Not Identified

Risk Level: L - Low Risk Surface: Woodchip







Action: Replace worn chains















4 - Very Low Risk (Finding 1)

Item: Outdoor Fitness Equipment - Leg Press
Manufacturer: The Great Outdoor Gym Company



Finding: There is some minor damage to the surface

Risk Level: V - Very Low Risk
Surface: Wet Pour



Action: Monitor for any further deterioration and repair as required

6

6 - Low Risk (Finding 2)

Item: Outdoor Fitness Equipment - Leg Press

Manufacturer: The Great Outdoor Gym Company



Finding: There is minor distortion damage to the item

Risk Level: L - Low Risk Surface: Wet Pour



Action: Monitor and repair if required







Item:Outdoor Fitness Equipment - Ab StationRisk Level:L - Low RiskManufacturer:The Great Outdoor Gym CompanySurface:Wet Pour



Finding: The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting

Action: Treat any rusting components and repaint



Item:Outdoor Fitness Equipment - Ab StationRisk Level:L - Low RiskManufacturer:The Great Outdoor Gym CompanySurface:Wet Pour





Finding: There is minor distortion damage to the bench

Action: Monitor and repair if required


























Finding: The deflection of the rotating user station exceeds Action: Monitor - No remedial work recommended the maximum 105 degrees required by BS EN 16630









Item:Outdoor Fitness Equipment - Hip TwisterRisk Level:M - Moderate RiskManufacturer:The Great Outdoor Gym CompanySurface:Wet Pour





Finding: The central support is missing

Action: Replace the missing support or remove the item completely

6 - Low Risk (Finding 1)

Item:Outdoor Fitness Equipment - Hand BikeRisk Level:L - Low RiskManufacturer:The Great Outdoor Gym CompanySurface:Wet Pour





Finding: There is minor damage to the seat

Action: Monitor and replace if required
















8 - Low Risk (Finding 2)

Item:Outdoor Fitness Equipment - TreadmillRisk Level:L - Low RiskManufacturer:The Great Outdoor Gym CompanySurface:Wet Pour







Action: Replace the missing inspection plate

L - Low Risk

Wet Pour



6 - Low Risk (Finding 1)

Item: Outdoor Fitness Equipment - Pull Up Risk Level:

Station

Manufacturer: The Great Outdoor Gym Company Surface:



Finding: The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting



Finding: The paintwork on this item has been damaged or Action: Treat any rusting components and repaint








Outdoor Fitness Equipment - Dip Station Risk Level: L - Low Risk Item: The Great Outdoor Gym Company Surface: Wet Pour Manufacturer:





Finding: The paintwork on this item has been damaged or Action: Treat any rusting components and repaint worn exposing the metal underneath which is rusting



Item: Outdoor Fitness Equipment - Cross Trainer Risk Level: L - Low Risk Manufacturer: The Great Outdoor Gym Company Surface: Wet Pour




Finding: There is or are fixings missing on the item

Action: Replace all missing fixings





















5 - Very Low Risk (Finding 1)

Multi Use Games Area - Goalmouth and Risk Level: V - Very Low Risk Item: **Basketball Post**

Manufacturer: Wet Pour Park Leisure Ltd Surface:





Finding: A clearly visible facility sign should be provided in Action: Provide signage to BS EN 15312 a prominent position with the wording as detailed BS EN 15312- the equipment is not intended for children less than 3 years old- the warning - Do not climb on the framework or nets- the warning - Do not hang on the ring (if provided)- the warning - Do not wear rings or other jewellery- name and telephone number of the administrator- number to call in case of accident







5 - Very Low Risk (Finding 2)

Item: Multi Use Games Area - Goalmouth and Basketball Post

Manufacturer: Park Leisure Ltd

Risk Level: V - Very Low Risk

Surface: Wet Pour



Finding: There is/are finger entrapments in the mesh openings and the item fails to meet the requirements of BS EN 15312 Clause 4.4.2.2 Entrapment of fingers



Action: Monitor - No remedial work recommended



2 - Very Low Risk (Finding 3)

Multi Use Games Area - Goalmouth and

Basketball Post

Manufacturer: Park Leisure Ltd

Risk Level: V - Very Low Risk

Surface: Wet Pour



Finding: There is some graffiti present



Action: Remove the graffiti







Item: Multi Use Games Area - Goalmouth and Basketball Post


Manufacturer: Park Leisure Ltd

Risk Level: L - Low Risk

Wet Pour

Surface:







Action: Clean and treat appropriately





3 - Very Low Risk (Finding 1)

Item: Multi Use Games Area - Kickabout Wall Risk Level: V - Very Low Risk

Manufacturer: Park Leisure Ltd Surface: Wet Pour






Finding: A clearly visible facility sign should be provided in a prominent position with the wording as detailed BS EN 15312- the equipment is not intended for children less than 3 years old- the warning - Do not climb on the framework or nets- the warning - Do not hang on the ring (if provided)- the warning - Do not wear rings or other jewellery- name and telephone number of the administrator- number to call in case of accident


Annual Inspection for Thurrock Council at Corringham Town Park Springhouse Road, Corringham, Essex, SS17 7NB

Inspected on the 31-July-2021 - 04:31















Item:Multi Use Games Area - Kickabout WallRisk Level:Manufacturer:Park Leisure LtdSurface:



L - Low Risk

Finding: The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting

Action: Treat any rusting components and repaint